

Work Order ID 155756

155756

Page 1

Wednesday, January 18, 2017 7:35:42 AM

Item ID: D350-588-011 Accept *N900040100* Setup Start *NS1*
 Revision ID: Stop *NS2*
 Item Name: Aft Door Fwd Hinge Modification
 Start Date: 1/9/2017 Start Qty: 5.00 *5* Cust Item ID:
 Required Date: 1/17/2017 Req'd Qty: 5.00 *5* Customer:
 Reference: DAS 21

Approvals: Process Plan: 9-89 Date: JAN 20 2017 Tooling: Date: Run Start *NR1*
 QC: Date: SPC (Y/N): Date: Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D350-588	D							DAS 21 9-89	17-02-14
DSI9690	A								
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefile and create labels per PPP D350-588-011 CHG002								
110	Pick Kit	0.00							
110									
Packaging	Memo	0.00							
Packaging									

5x DAS 28 9-89

5 FEB 14 2017 DAS 6 9-89 DAS 27 9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabelled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Work Order ID 155756***155756***

Page 2

Wednesday, January 18, 2017 7:35:42 AM

Item ID: D350-588-011

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017 Start Qty: 5.00

5

Cust Item ID:

Required Date: 1/17/2017 Req'd Qty: 5.00

5

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120	QC4- 100% Inspect kits for completeness	0.00							
120						5x	DAS 28 9-89		FEB 16 2017
QC	Memo	0.03							
Quality Control									
130		0.00							
130	Packaging					5x	DAS 28 9-89	DAS 27 9-89	FEB 16 2017
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D350-588-011 Location :FG022								
							DAS 21 9-89		
140	QC21- Final Inspection - Work Order Release	0.00							FEB 16 2017
140									
QC	Memo	0.08							
Quality Control									
							DAS 21 9-89		FEB 16 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
				Completed By					
				Lead hand / Supervisor Approval Verification					
				QC / QA Coordinator Approval					

Root Cause				FAULT CATEGORY			
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong		
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions		
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance		
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect		
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing		
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved		
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing		
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Mislabeled	☐ Finish		
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread		
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence		
Past Expiry Date ☐	☐ Manufacturing Process	OTHER : _____					
Misidentified ☐	☐ Past Due						

Picklist Print

Tuesday, January 17, 2017 1:17:29 PM

Page 1

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

Comments: IPP Rev:M04.08.31Added D2690-17KJ/JLM IPP REV:G
14.04.28 AS PER DSI9690 DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN526C1032R7 Screw		Purchased	No			120	Each	136.0000	2	10			
AN526C1032R7													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST327		136							
					M128403	136							
AN526C832R8 Screw		Purchased	No			120	Each	184.0000	8	40			
AN526C832R8													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST327		184							
					m134376	84							
					m135978	100							
AN526C832R9 Screw		Purchased	No			120	Each	413.0000	8	40			
AN526C832R9													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				over006		200							
					M134962	200							
				ST327		213							
					M135766	63							
					M136301	150							

FEB 14 2017
DAS 27
9-89

FEB 14 2017
DAS 27
9-89

FEB 14 2017
DAS 27
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Tuesday, January 17, 2017 1:17:30 PM

Page 2

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

D2143 Manufactured No

120 Each

29.0000

1 5

D2143

Hinge Bracket

DAS
28
9-89

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST002

29

141033

7

150285

12

152427

10

D2144 Manufactured No

120 Each

28.0000

1 5

D2144

Hinge Doubler

DAS
28
9-89

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST002

28

141066

8

150971

20

D2150 Manufactured No

120 Each

37.0000

2 10

D2150

Packer Doubler, Hinge

DAS
28
9-89

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST002

17

141069

17

ST003

20

152300

20

D2151 Manufactured No

120 Each

42.0000

2 10

D2151

Packer Doubler

DAS
28
9-89

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST002

42

141044

22

152281

20

Tuesday, January 17, 2017 1:17:30 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong		
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions		
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance		
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect		
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing		
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved		
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing		
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Mislabeled	☐ Finish		
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread		
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence		
Past Expiry Date ☐	☐ Manufacturing Process	OTHER : _____					
Misidentified ☐	☐ Past Due						

Picklist Print

Tuesday, January 17, 2017 1:17:30 PM

Page 3

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

D2153 Manufactured No

120 Each

33.0000

1 5

D2153

Door Prop

DAS
28
9-89

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST362

33

152433

33

D2154 Manufactured No

120 Each

30.0000

1 5

D2154

Bracket, Stud

DAS
28
9-89

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST003

30

118894

5

145373

14

152222

11

D2237 Manufactured No

120 Each

67.0000

2 10

D2237

Striker Plate

DAS
28
9-89

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST004

67

150093

17

152168

20

153454

10

154292

20

D2461 Manufactured No

120 f

345.0772

1.25 38.15789

D2461

Neoprene 'D' Seal (\$Per Foot)

DAS
38
-89

DAS
28
9-89

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

Location

Loc Qty

Loc Code

ST407

345.0772268

144533

345.077227

Tuesday, January 17, 2017 1:17:30 PM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Tuesday, January 17, 2017 1:17:30 PM

Page 4

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

D2463 Manufactured No 120 f 478.2506 7.25 38.15789

D2463

1/2" Seal (\$ per foot)

DAS
28
9-89

Location

Loc Qty

Loc Code

ST409

478.2506391

140013

0.00063908

148875

478.25

120 Each

49.0000

2

10

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

D2583 Manufactured No 120 Each 49.0000 2 10

D2583

Latch Bracket

DAS
28
9-89

Location

Loc Qty

Loc Code

ST481

49

152314

24

154221

25

120 Each

65.0000

2

10

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

D2585 Manufactured No 120 Each 65.0000 2 10

D2585

Latch Clamp

DAS
28
9-89

Location

Loc Qty

Loc Code

ST008

28

149785

2

150470

11

154228

15

ST012a

37

152338

15

152476

22

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

Tuesday, January 17, 2017 1:17:30 PM

Shop Packet Print

Page 4

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
					QC / QA Coordinator Approval				

Root Cause				FAULT CATEGORY			
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐
Past Expiry Date ☐	☐	Manufacturing Process	☐	OTHER : _____			
Misidentified ☐	☐	Past Due	☐				

Picklist Print

Tuesday, January 17, 2017 1:17:30 PM

Page 5

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

D2586 Manufactured No 120 Each 90.0000 **2** 10
D2586 ****** **DAS 6 9-89** **FEB 14 2017**
Door Latch

Location	Loc Qty	Loc Code
FG	12	
139228	8	
152211	4	
ST481	18	
152211	18	70
ST486a	50	
153582	25	
154875	25	
ST488a	10	
150060	10	

D2587 Manufactured No 120 Each 29.0000 **1** 5
D2587 ****** **DAS 6 9-89** **FEB 14 2017**
Door Plug

Location	Loc Qty	Loc Code
ST008	29	
150316	9	5
152274	10	
154216	10	

D2589 Manufactured Yes 120 Each 58.0000 **1** 5
D2589 ****** **DAS 6 9-89** **FEB 14 2017**
Keys, Key Chain

Location	Loc Qty	Loc Code
ST008	58	
132942	58	5

Tuesday, January 17, 2017 1:17:30 PM

Shop Packet Print

Page 5

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Tuesday, January 17, 2017 1:17:30 PM

Page 6

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

D2690-17 Manufactured No

120

Each

24.0000

1

5

D2690-17

Cable

DAS
6
9-89
FEB 14 2017
DAS
27
9-89

Location

Loc Qty

Loc Code

ST009

1

140042

1

ST012a

23

142810

9

150107

4

152174

10

D2857-1

Manufactured No

120

Each

40.0000

1

5

D2857-1

Hinge Bracket

DAS
6
9-89
FEB 14 2017
DAS
27
9-89

Location

Loc Qty

Loc Code

FG

5

144748

1

150331

3

91914

1

ST012a

35

150331

11

152448

24

D2857-2

Manufactured No

120

Each

34.0000

1

5

D2857-2

Hinge Bracket

DAS
6
9-89
FEB 14 2017
DAS
27
9-89

Location

Loc Qty

Loc Code

FG

3

140972

2

78904

1

ST012

7

144616

7

ST012a

24

152184

24

Tuesday, January 17, 2017 1:17:30 PM

Shop Packet Print

Page 6

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval	
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER :							
Misidentified ☐	Past Due ☐								

Picklist Print

Tuesday, January 17, 2017 1:17:30 PM

Page 7

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

D2858-1

Manufactured No

120

Each

28.0000

1

5

D2858-1

Hinge Bracket

**

FEB 14 2017

DAS
6
9-89

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST012

16

140966

1

150112

15

ST012a

12

152740

12

41

D2858-2

Manufactured No

120

Each

36.0000

1

5

D2858-2

Hinge Bracket

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

DAS
23
9-89

Location

Loc Qty

Loc Code

FG

2

77020

2

ST012

10

141043

3

145856

7

ST012a

24

152277

24

32

D5080-041

Manufactured No

120

Each

9.0000

2

10

D5080-041

Striker Plate Assembly

**

DAS
6
9-89

FEB 14 2017

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST148

9

143432

9

9

Tuesday, January 17, 2017 1:17:30 PM

Shop Packet Print

Page 7

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
				Completed By _____					
				Lead hand / Supervisor Approval Verification _____					
				QC / QA Coordinator Approval _____					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Tuesday, January 17, 2017 1:17:30 PM

Page 8

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

FG-778150-550-ROL

Purchased

No

120

sf

1,107.166

1

6.666667

***FG-778150-550-ROL ***

7781 9 oz Glass 50" x 125 yd

DAS
28
9-89

Location

Loc Qty

Loc Code

CA2

1107.166712

M127701

4.00004485

M134550

1103.16667

**

FEB 14 2017

DAS
6
9-89
DAS
27
9-89

MS20426AD3-4

Purchased

No

120

Each

8,848.000

12

60

MS20426AD3-4

RIVET

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

4885

m136444

4885

ST312

3963

m134294

3963

**

FEB 14 2017

DAS
6
9-89
DAS
27
9-89

MS20470AD4-5

Purchased

No

120

Each

883.0000

18

90

MS20470AD4-5

RIVET, UNIVERSAL HEAD

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

37

m133860

37

ST310

846

m134654

846

**

FEB 14 2017

DAS
6
9-89
DAS
27
9-89

Tuesday, January 17, 2017 1:17:30 PM

Shop Packet Print

Page 8

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong		
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions		
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance		
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect		
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing		
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved		
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing		
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Mislabeled	☐ Finish		
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread		
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence		
Past Expiry Date ☐	☐ Manufacturing Process	OTHER : _____					
Misidentified ☐	☐ Past Due						

Picklist Print

Tuesday, January 17, 2017 1:17:30 PM

Page 9

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

MS21042L08

Purchased

No

120

Each

821.0000

18

90

MS21042L08

Nut

**

FEB 14 2017

Location

Loc Qty

Loc Code

GA

509

m135274

18

m135978

491

ST303

312

m136301

192

m136537

120

136791

DAS
28
9-89

DAS
6
27
9-89

MS21042L3

Purchased

No

120

Each

1,970.000

4

20

MS21042L3

Nut

**

FEB 14 2017

Location

Loc Qty

Loc Code

FP001

100

m135945

100

GA

162

m134360

108

m135135

54

OVER007

500

M136554

500

ST303

1208

M136044

108

M136192

600

M136406

500

20

FEB 14 2017

DAS
6
27
9-89

DAS
27
9-89

MS27039-08-11

Purchased

No

120

Each

235.0000

2

10

MS27039-08-11

SCREW

**

Location

Loc Qty

Loc Code

ST278

235

m135864

235

10

DAS
28
9-89

DAS
6
27
9-89

DAS
27
9-89

Tuesday, January 17, 2017 1:17:30 PM

Shop Packet Print

Page 9

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong				
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions				
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance				
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect				
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing				
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved				
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing				
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Misabeled	☐ Finish				
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread				
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence				
Past Expiry Date ☐	☐ Manufacturing Process	OTHER :							
Misidentified ☐	☐ Past Due								

Picklist Print

Page 10

Tuesday, January 17, 2017 1:17:30 PM

Work Order ID: 155756

155756

Parent Item: D350-588-011

D350-588-011

Parent Item Name: Aft Door Fwd Hinge Modification

Start Date: 1/9/2017

Required Date: 1/17/2017

Start Qty: 5.00

Required Qty: 5.00

MS27039-1-15

Purchased

No

120

Each

265.0000

2

10

MS27039-1-15

Screw

**

FEB 14 2017

DAS
6
9-89

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

1

m127916

1

over006

100

m136554

100

ST280

164

m134852

64

m136406

100

NAS1149D0363J

Purchased

No

120

Each

1,128.000

4

20

NAS1149D0363.J

Washer

**

FEB 14 2017

DAS
6
9-89

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

272

m134055

272

ST263

856

m136318

856

NAS1149DN832J

Purchased

No

120

Each

1,558.000

24

120

NAS1149DN832.J

Washer

**

FEB 14 2017

DAS
6
9-89

DAS
27
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST264

1558

M135297

1558

Tuesday, January 17, 2017 1:17:30 PM

Shop Packet Print

Page 10

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong				
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions				
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance				
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect				
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing				
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved				
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing				
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Mislabeled	☐ Finish				
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread				
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence				
Past Expiry Date ☐	☐ Manufacturing Process	OTHER : _____							
Misidentified ☐	☐ Past Due								

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D350-588 REV. D AND
INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D350-588 REV. D
REF TCCA STC SH92-41
FAA STC SH1012NE

SHOP COPY
 RETURN TO
 ENGINEERING
 UNCONTROLLED COPY
 SUBJECT TO AMENDMENT
 WITHOUT NOTICE
 WORK ORDER
 NO. 155156.415
 1701-20

1.0 PURPOSE:

The purpose of this Dart Service Instruction is to provide customers with directions to install a modified striker plate that will provide more clearance around environmental/conductive seals that protrude inboard of the door frame structure on AS355 N/NP models.

2.0 PROCEDURE:

- 1) Install D350-588-011/-041 per Section 3.1/3.2 of D350-588 as applicable, except do not install D2237 striker plates per item 10 of Section 3.1.
- 2) Remove the aft environmental/conductive seal to gain access to the door structure.
- 3) Using a fine point marker, mark location of both striker plates based on door latch location.
- 4) If D2237 Striker Plates are currently installed, remove both striker plates by drilling out rivets.
- 5) Align D5080-041 striker plate assembly in the previously marked location and transfer drill the $\varnothing 0.1285"$ (#30) holes into the aft bulkhead.
- 6) Drill out both rivets on the aircraft skin adjacent to the striker plate assemblies.
- 7) Align D5080-041 striker plate assembly in the previously marked location and transfer drill the $\varnothing 0.1285"$ (#30) holes from the aircraft skin to the striker plate assembly.
- 8) Deburr holes and remove all sharp edges.
- 9) Touch up all holes in aluminum with chemical conversion coating in accordance with MIL-DTL-5541.
- 10) Apply 0.125" thick layer of PR-1775B ProSeal to the face of D5080-041 per Figure 1.
- 11) Install D5080-041 striker plate assemblies to the aft bulkhead using CR3213-4 rivets of a suitable length, and to the skin of the aircraft using PR-1775B coated CR3213-4 rivets of a suitable length.
- 12) Reinstall environmental/conductive seal using manufacturers recommended procedure.
- 13) Install gas strut or cable assembly per D350-588 Figure 5.
- 14) Adjust both latch mechanisms to ensure adequate compression of door seal and that door skin is flush.
- 15) Check door for proper operation by opening and closing the door, and ensure latches fully lock.




Figure 1 Striker Plate

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO #01-O-01

APPROVED

BY: *[Signature]*
D. SHEPHERD (DE # 02)

DATE: 14.03.24
CERT. NO.: SH82-41
ISSUE NO.: 8

A	NEW ISSUE	ML	14.03.24
REV.	DESCRIPTION	BY	DATE
DESIGN	ML	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	ML		
CHECKED	<i>[Signature]</i>	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9690	SHEET 1 OF 2
APPROVED	<i>[Signature]</i>	TITLE	SCALE
DE APPR.	<i>[Signature]</i>	STRIKER PLATE MOD	NTS
DATE	14.03.24	COPYRIGHT © 2014 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

3.0 PARTS LIST:

The part lists of D350-588 Rev. D and ICA-D350-588 Rev. 0 are amended as follows.

IS:

588 -041	588 -011	PART NUMBER	DESCRIPTION
X		D350-588-041	AFT DOOR ASSEMBLY
	X	D350-588-011	AFT DOOR FWD HINGE MOD
2	2	D5080-041	STRIKER PLATE ASSY (AS355 N/NP MODELS ONLY)
2	2	D2237	STRIKER PLATE

WAS:

588 -041	588 -011	PART NUMBER	DESCRIPTION
X		D350-588-041	AFT DOOR ASSEMBLY
	X	D350-588-011	AFT DOOR FWD HINGE MOD
2	2	D2237	STRIKER PLATE

Customers who need to upgrade a D350-588-011/-041 kit that has been previously purchased from Dart can procure the DSI 9690-011 Kit from Dart.

QTY -011	PART NUMBER	DESCRIPTION
X	DSI 9690-011	STRIKER PLATE MODIFICATION KIT
2	D5080-041	STRIKER PLATE ASSEMBLY

4.0 WEIGHT AND BALANCE:

This DSI has a negligible effect on Weight and Balance of the aircraft.

5.0 MAINTENANCE:

Maintain the D5080-041 Striker Plates in accordance with the procedures for the D2237 Striker Plates as outlined in ICA-D350-588.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: 
D. SHEPHERD (DE # 02)

DATE: 14.03.24
CERT. NO.: SH92-41
ISSUE NO.: 8

DESIGN	ML	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
DRAWN	ML	
CHECKED		DRAWING NO. REV. A
MFG. APPR.	N/A	DSI 9690 SHEET 2 OF 2
APPROVED		TITLE SCALE
DE APPR.		STRIKER PLATE MOD NTS
DATE	14.03.24	COPYRIGHT © 2014 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

3.3 WEIGHT AND BALANCE

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
D350-588-011	1.0 lb	-21.0 in	-21.0 in-lb	+170.0 in	+170.0 in-lb
Aft Door Fwd Hinge Modification Kit	0.45 Kg	-0.53 m	-0.24 m-Kg	+4.32 m	+1.96 m-Kg
D350-588-041*	2.0 lb	-21.0 in	-42.0 in-lb	+170.0 in	+340.0 in-lb
Aft Door Assembly	0.91 Kg	-0.53 m	-0.48 m-Kg	+4.32 m	+3.93 m-Kg

* D350-588-041 Aft Door Assembly weight in excess of standard Eurocopter Door.

3.4 PARTS LISTS

588 -041	588 -011	Part Number	Description
X		D350-588-041	AFT DOOR ASSEMBLY
	X	D350-588-011	AFT DOOR FWD HINGE MODIFICATION KIT
1	1	D2143	HINGE DOUBLER
1	1	D2144	HINGE DOUBLER
2	2	D2150	HINGE PACKER
2	2	D2151	HINGE DOUBLER
1	1	D2153-3315-10	GAS SPRING ASSY.
1	1	D2154	STUD BRACKET
2	2	D2237	STRIKER PLATE
1		D2445	DOOR
1	1	D2461-0870	NEOPRENE D SEAL
1	1	D2463-0870	½" FOAM SEAL
	2	D2583	LATCH BRACKET
2	2	D2585	LATCH CLAMP
2	2	D2586	LATCH
	1	D2587	PLUG
1	1	D2589	KEYS, KEY CHAIN
2		D2621	LATCH PLATE
1	1	D2690-17	CABLE, DOOR STOP
1	1	D2857-1	LOWER HINGE BRACKET
1	1	D2857-2	UPPER HINGE BRACKET
1	1	D2858-1	LOWER HINGE BRACKET
1	1	D2858-2	UPPER HINGE BRACKET
8	8	AN526C832R8	SCREW (or AN526-832R8)
8	8	AN526C832R9	SCREW (or AN526-832R9)
2	2	AN526C1032R7	SCREW (or AN526-1032R7)
24	24	AN960JD8	WASHER
4	4	AN960JD10	WASHER
12	12	MS20426AD3-4	RIVET
18	18	MS20470AD4-5	RIVET
18	18	MS21042L08	NUT (or MS21042-08)
4	4	MS21042L3	NUT (or MS21042-3)
2	2	MS27039-1-15	SCREW
2	2	MS27039-0811	SCREW
1	1	N/A	1 SQUARE ft. OF 9 oz. GLASS CLOTH (S-CLASS)

• COPYRIGHT © 1992 BY DART AEROSPACE LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: D
Date: 02.01.17

3.0 PARTS LIST:

The part lists of D350-588 Rev. D and ICA-D350-588 Rev. 0 are amended as follows.

IS:

588 -041	588 -011	PART NUMBER	DESCRIPTION
X		D350-588-041	AFT DOOR ASSEMBLY
	X	D350-588-011	AFT DOOR FWD HINGE MOD
2	2	D5080-041	STRIKER PLATE ASSY (AS355 N/NP MODELS ONLY)
2	2	D2237	STRIKER PLATE

WAS:

588 -041	588 -011	PART NUMBER	DESCRIPTION
X		D350-588-041	AFT DOOR ASSEMBLY
	X	D350-588-011	AFT DOOR FWD HINGE MOD
2	2	D2237	STRIKER PLATE

Customers who need to upgrade a D350-588-011/-041 kit that has been previously purchased from Dart can procure the DSI 9690-011 Kit from Dart.

QTY -011	PART NUMBER	DESCRIPTION
X	DSI 9690-011	STRIKER PLATE MODIFICATION KIT
2	D5080-041	STRIKER PLATE ASSEMBLY

4.0 WEIGHT AND BALANCE:


This DSI has a negligible effect on Weight and Balance of the aircraft.

5.0 MAINTENANCE:

Maintain the D5080-041 Striker Plates in accordance with the procedures for the D2237 Striker Plates as outlined in ICA-D350-588.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: 
D. SHEPHERD (DE # 02)

DATE: 14.03.24
CERT. NO.: SH92-41
ISSUE NO.: 8

DESIGN	ML	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
DRAWN	ML	
CHECKED		DRAWING NO. REV. A
MFG. APPR.	N/A	DSI 9690 SHEET 2 OF 2
APPROVED		TITLE SCALE
DE APPR.		STRIKER PLATE MOD NTS
DATE	14.03.24	COPYRIGHT © 2014 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.